Port of:

Das Zirku & Mubarraz

Port Marine Notice

No. DZM/MN/039/2018

20/08/2018

To:

All Shipping

Port Users

Shipping Agents
Port Operators

Subject: Mooring buoys

Please be advised that, mooring buoys are located at the following positions

Buoy Name	Light Characteristics	Latitude	Longitude	Туре
Z-1	Unlit	24° 50.71′ N	053° 05.43′ E	Mooring Buoy
Z-2	Unlit	24° 51.26′ N	053° 05.57′ E	Mooring Buoy
Nil	Yellow	24° 51.59′ N	053° 05.42′ E	Mooring Buoy

Following Buoy has been removed from the following location

Buoy Name	Light Characteristics	Latitude	Longitude	Туре
Nil	Unlit	24° 50.89′ N	053° 05.77′ E	Mooring Buoy

Caution: Mariners are to exercise caution whilst transiting this area and keep a continuous listening watch on VHF channels 12/23 (Das Port Control/VTIS).

Any clarification related to this **Port Marine Notice**, may be directed to the Harbor Master at Tel: **+971 260 28999**

Harbour Master

Issue: 01/Oct-2017

Port of:

Das Zirku & Mubarraz

Rev: 0

Page 1 of 1