

Port Marine Notice

Port of: **Das Zirku & Mubarraz**

No. DZM/MN/012/2024

Date: 17/04/2023

To: **All Shipping
Shipping Agents
Port Users
Port Operators**

Type of Change: **Temporary**

Subject: Mooring Buoy Drifted

The tug mooring buoy near Zirku terminal is drifted from it's original location.

Name	Charted Position		Drifted Location as on 17.04.2024		Lights
	Latitude	Longitude	Latitude	Longitude	
CZ-4	025° 02.74' N	053° 00.45' E	025° 02.87' N	053° 00.24' E	Unlit

All vessels and crafts are requested to navigate with caution while transiting near anchor storage locations. Buoy may continue to drift from its reported position.

Caution: When in the vicinity of the location mariners are reminded to:

- a) Maintain a proper lookout, proceed at safe speed, and navigate with caution
- b) Keep well clear from the Mooring buoy area.
- c) Maintain a listening watch on VHF Channel 23 (Das VTIS)

Any clarification related to this Port Marine Notice, may be directed to the Harbor Master using Contact us form on PPA website <https://ppa.adnoc.ae/en/contact-us>

Harbor Master



Port of: **Das Zirku & Mubarraz**



