

Port Marine Notice

Port of: **Das Zirku & Mubarraz**

No. **DZM/MN/006/2025**

Date: **25/02/2025**

To: **All Shipping
Shipping Agents
Port Users
Port Operators**

Type of Change: **Temporary**

Subject: Midi buoy drifted

Please be advised that Midi buoy has drifted from its original position.

| Buoy Name | Charted Positions | | |
|-----------|-------------------|---------------|-----------------------|
| | Latitude | Longitude | Characteristics |
| MIDI 018 | 25° 03.005'N | 053° 04.159'E | Yellow - FL (5) Y.20s |

All Vessels are requested to navigate with caution and to maintain proper lookout while navigating in the vicinity. **Buoy may continue to drift from its reported position.**

Caution: When in the vicinity of the location mariners are reminded to:

- a) Maintain a proper lookout.
- b) Proceed at safe speed and navigate with caution.
- c) Maintain a listening watch on VHF Channel 12/ 23.

Any clarification related to this Port Marine Notice, may be directed to the Harbor Master using Contact us form on PPA website <https://ppa.adnoc.ae/en/contact-us>

Harbor Master

Port of: **Das Zirku & Mubarraz**



